

Gas Fireplace

650, 750, SS850, 950, 1250

ERROR CODES

Code	Probable Cause	Action
00	Mains power failure	Reset heater. Press ON/OFF button on the control panel/remote control/App twice - to turn the fire back on
11	Ignition failure	Check that the gas supply is turned on. Switch the heater to STANDBY and then ON again. If the error persists, a Service call will be required
12	Incomplete combustion	As above
14	Inlet Blockage / Overheat	Clean inlet, if the error persists, a service call will be required
16	Room overheat	Lower room temp to below 40°C
31	Room temperature sensor faulty	Service call
32	Overheat temperature 1 sensor faulty	Service call
33	Overheat temperature 2 sensor faulty	Service call
53	Spark sensor faulty	Service call
61	Combustion fan motor faulty	Service call
71	Solenoids faulty	Service call
72	Flame detection circuit fault	Service call
73	Communication error	Service call