

Portable Gas Heaters

Avenger 25, Dynamo 15, Enduro 13 and Granada 252

ERROR CODES

Code	Probable Cause	Suggested Remedy
0	Mains power failure during operation	Press the ON/OFF button twice to reset heater
3	Tilt switch activated	Ensure appliance is level and upright. Service call if repeated
10	Oxygen shortage	Clean filters. Ventilate room. Service call if repeated
11	Ignition failure	Check gas supply is turned on, turn the heater OFF and then ON again. If the heater fails to ignite after 4 attempts a Service call will be required
12	Incomplete combustion	As above
13	Combustion control faulty	Service call
14	Filter Blockage / Overheat	Clean filters. If error continues a Service call will be required
16	Room overheat	Lower room temp to below 40°C
18	Thermocouple output error	Lacking in gas supply or incorrect gas type or Service call
31	Room temperature sensor faulty	Service call
32	Overheat temperature sensor faulty	Service call
33	Overheat temperature sensor faulty	Service call

34	Overheat temperature sensor faulty	Service call
62	Faulty fan motor	Service call
70	ON/OFF switch faulty	Service call
71	Solenoids faulty	Service call
72	Flame detection circuit fault	Service call
73	Communication error	Press the ON/OFF button twice to reset heater